## **MAC Aura XB - Maintenance Schedule** Maintenance schedule vers. 1.0.1 -Level 1 **Total lamp hours** Part description 750 1500 2250 3000 3750 4500 5250 6000 6750 7500 8250 **9000** 9750 10500 11250 12000 12750 13500 14250 15000 15750 16500 17250 **18000** hrs Contact Contact С Head - general С Fans & Cooling Plate С С С С С С С С С С X t Martin Martin С С С С С С С С С С Front Lens 1) U Light Rods R Professional Professional Е Zoom motors Wireset Ε Α D Yoke - general Pan & Tilt belt 0 Pan & Tilt belt tightening system Wire harness Pan and yoke bearing Base - general SMPS В Base fan С С С С С С С С С С s Ε Fixture software 1 1 2 1 Technician skill level 1 1 1

r	_	_	_	=	•	=	_	_	-

Ambient temperature	40°C
Voltage / frequency	Within specified range for the product

## Code

I	Inspect
R	Replace
С	Clean
L	Lubricate
Α	Adjust
U	Update

Only cleaning on the outside.

Important! Do not use concentrated alcohol solutions, abrasive products or solvents to clean the lens. If wiping with a soft, lint-free cloth dampened with distilled water is not effective, dampen the cloth with distilled water containing 20% isopropyl alcohol in solution.