

Martin Playback II Module firmware for version 3.70.885

Introduction

This document lists all available firmware for a Martin Playback II Module, working on the M-Series software release version 3.70.885

USB firmware

(F0A9) USB-DMX2P (V3.42).C2

(F0AA) M-DMX (V3.42).C2

(F0B1) Desklight Module (V3.40) USB.C2

(F10A) Playback Module II (V3.40) USB.C2

IIC firmware

(1x-F10A-21) Playback II Motor Fader (V3.40) IIC.hex

(20-F10A-11) Playback II Playbacks (V3.41) IIC.hex

